

Fog Machine Chiller

Materials:

- 1 10 gal storage tub
- 2ft Chicken wire
- 2 PVC couplings

Optional:

- Computer Fan



Step 1

- Cut the chicken wire so it fits in the Tub
- Best way to flip the tub over and cut long the sides
- Then trim it down so it fits tightly in the middle
- (optional) Add Duct tape to the sides (easier handling and easy to hot glue)



Step 2

- It's time for you to decide where you want your chilled fog to exit the chilling box (keep in mind the entrance will be on one of the narrow sides of the box). Take one of the couplings and trace a circle there.
- Next, take the other coupling and measure a circle near the top of the box. Line up the top hole so that the opening faces into the box the long way
- Drill out the holes
- Insert the Couplings and hot glue them in place
- Make sure there is no air escape the outside of the coupling



Step 3 (optional)

- Hot Glue the Computer Fan inside the tub on the exit
It Helps the fog leave the chiller
(forgot to take a photo for this step)

Step 4

- Hot Glue the Chicken Wire Half way down the tub making sure there are 2 chambers enough air on the top where the ice will lay and one for the bottom where the fog with gather



Step 5

- Add ice
- Turn on the fan
- Close the lid and watch the effect

